

**STATEMENT OF WORK FOR THE
REBUILD
OF THE
M40A1
SNIPER RIFLE, 7.62MM
1005-01-035-1674**

Document Control Number: SOW-04-CBG-05539B-1/1

Date: 12 September 2001

TABLE OF CONTENTS

Paragraph	CONTENTS	PAGE
1.0	SCOPE	1
1.1	Background	1
2.0	APPLICABLE DOCUMENTS	1
2.1	Military Standards	1
2.2	Other Government Documents And Publications	1
2.3	Industry Standards	2
3.0	REQUIREMENTS	2
3.1	General Tasks	2
3.2	Detailed Tasks	2
3.2.1	REBUILD	2
3.2.2	Inspection, Testing And Acceptance	3
3.2.3	Packaging, Handling, Storage, and Transportation	4
3.3	Government Furnished Equipment(GFE)/ Government Furnished Materiel (GFM)	4
3.4	Quality Assurance Provisions	5
3.5	Contractor Furnished Materiel	5
3.6	Acceptance	5
3.7	Rejection	5
4.0	REPORTS	5
4.1	Monthly Progress Reports	5
4.2	BRS Reporting	5

**STATEMENT OF WORK FOR THE
REBUILD OF THE
M40A1 SNIPER RIFLE, 7.62MM
1005-01-035-1674**

1.0 SCOPE. This Statement of Work (SOW), establishes and sets forth tasks and identifies the work efforts that shall be performed by the Contractor (for purposes of this SOW, the Contractor is defined as the commercial or government entity performing the REBUILD) in the REBUILD effort of the M40A1 Sniper Rifle 7.62MM, hereafter known as the M40A1. This document contains requirements to restore the M40A1 to Condition Code "A." Condition Code A is defined as "serviceable/issuable without qualification, new, used, repaired or reconditioned materiel which is serviceable and issuable to all customers without limitation or restriction, including materiel with more than 6 months shelf-life remaining."

1.1 Background. REBUILD is defined as "That maintenance technique to restore an item to a standard as near as possible to original or new condition in appearance, performance, and life expectancy. This is accomplished through a maintenance technique or complete disassembly of the item, inspection of all parts or components, repairs or replacement of worn or unserviceable elements using original manufacturing tolerances and/or specifications and subsequent reassembly of the items."

2.0 APPLICABLE DOCUMENTS. The following documents form a part of this SOW to the extent specified. Unless otherwise specified, the issues of these documents are those listed in the Department of Defense Index of Specifications and Standards (DoDISS) and supplement thereto which is in effect on the date of solicitation. In the event of conflict between the documents referenced herein and the contents of this SOW, the contents of this SOW shall be the superseding requirement.

2.1 Military Standards

MIL-STD-129	DoD Standard Practice for Military Marking
MIL-STD-2073-1D	DoD Standard Practice for Military Packaging

2.2 Other Government Documents and Publications. The issues of those documents cited below shall be used.

TM 09629A-23&P/2A	Organizational and Intermediate Maintenance Manual including Repair Parts List, Sniper Rifle, 7.62 MM M40A1
DoD 4000.25-1-M	MILSTRIP Manual

2.3 Industry Standards

ANSI/ISO/ASQC
Q9002-1994

Quality Systems-Model for Quality Assurance in
Production Installation and Servicing

Copies of Military Specifications and Standards are available from DOD Single Point, Document Automation and Production Services, Building 4/D, Robbins Avenue, Philadelphia, PA 19111-5094, Telephone (215) 697-2179 or DSN 442-2179, or <http://www.dodssp.daps.mil>. Copies of other government documents and publications required by contractors in connection with specific SOW requirements shall be obtained through the Contracts Department, (Code 891), P. O. Drawer 43019, 814 Radford Blvd., MCLB Albany, GA 31704-3019, commercial telephone number (229) 639-6613 or DSN 567-6613. Copies of engineering drawings, if applicable, shall be obtained from Supply Chain Management Center, (Code 583-1), 814 Radford Blvd., Suite 20320, Albany, GA 31704-0320, commercial telephone number (229) 639 6410 or DSN 567-6410.

3.0 REQUIREMENTS

3.1 General Tasks. In fulfilling the specified requirements, the Contractor shall:

a. Provide materials, labor, equipment, facilities and missing/repair parts, necessary to inspect, diagnose, restore, and test and calibrate the M40A1. Upon completion of REBUILD, the subject item shall be Condition Code "A".

b. Conduct in-process and final on-site testing for witness by a Marine Corps Systems Command (MCSC), (Code CBG), Albany, Georgia representative.

3.2 Detail Tasks. The following tasks describe the different phases for REBUILD of the M40A1.

3.2.1 Rebuild. Components or assemblies shall not be disassembled for replacement of mandatory parts unless that part has failed, or the component assembly wherein the part is located is disassembled for repair.

a. Hardware

(1) Replace broken, unserviceable and/or missing hardware including nuts, bolts, screws and washers. Unserviceable would include any of the above that failed to function properly.

(2) Scopes in other than Condition Code "A" or "B" will be replaced. Finish is not a criteria for condition coding.

(3) Mandatory replacement parts are as follows:

1005-00-999-8821	Firing Pin Assembly
1005-00-999-8850	Trigger Assembly

5305-00-983-6665	Screw Cap Socket Head
1005-00-999-8815	Cartridge Ejector
1005-00-999-8817	Ejector Spring
1005-00-999-8816	Ejector Pin
1005-00-022-9777	Sear Pin
1005-00-983-8270	Bolt Stop Pin
TBD	Swivel, Quick Release
TBD	Bipod Assembly
TBD	Butt Pad, Pachmayr
BSS101S1-12	Barrel, 16861 Remington, 700 Bolt Assembly

(4) Hardware normally supplied with commercial parts shall be used unless specifically prohibited.

(5) The below listed Supply System Responsibility equipment will be shipped along with the rebuilt weapon:

1005-01-453-3783	Cleaning Kit - 1
NAVMC 10558A	Weapon Record Book - 1
1095-01-353-1686	Carrying Case, Ridged - 1
1240-01-123-4730	Sight Telescopic, Unertl 10X -1
1005-00-714-1245	Sling Small Arms - 1
4933-00-652-9950	Extractor, Ruptured Cartridge - 1
TBD	Wrench, Swivel
TBD	Mount Rail
TBD	Rings, Scope
TBD	Wrench, Spanner

(6) Test Fire: 1 - Proof Round and Function Fire - 30 Rounds M118 to verify weapons function, reliability, and safety.

(7) Accuracy Firing Requirement: Test fire three groups of five shots each, from a range of 300 yards to the following accuracy standard (extreme spread):

<u>AMMO</u>	<u>ACCURACY REQUIREMENT</u>
M118LR	3"

3.2.2 Inspection, Testing and Acceptance

a. Inspection, Testing and Acceptance of the M40A1 will be conducted in accordance with TM 09629A-23&P/2A.

b. The Contractor shall be responsible for conducting required tests and shall ensure all necessary personnel are notified prior to completion the final acceptance. Acceptance tests shall be made on site by qualified quality assurance personnel.

c. The Contractor shall be responsible for correcting any deficiencies identified during inspection/testing. MCSC (Code CBG), Albany, Georgia, representatives may require the Contractor to repeat tests or portions thereof, if the original tests fail to demonstrate compliance with this SOW.

3.2.3 Packaging, Handling, Storage, and Transportation (PHS&T)

a. The Contractor shall be responsible for preservation and packaging of items being repaired under the terms of this statement of work. Items being prepared for long term storage or shipment to overseas destinations shall be preserved and packaged to the Level "A" requirements of MIL-STD-2073-1D, method 41. Exterior shipping containers for shipment to overseas destinations or for long term storage shall be fabricated from wood. Exterior shipping containers for domestic shipment and immediate use shall be tri-wall fiberboard boxes.

b. Marking for shipment and storage shall be in accordance with MIL-STD-129. Unit packs and immediate containers shall be labeled with 1 ½ X 4 inch labels and shall include the NSN, nomenclature, quantity, unit of issue, month and year of pack, condition code and serial number of the weapon. The exterior shipping container shall not be marked with any data which will identify the contents of the container. Exterior shipping containers shall be marked with the quantity, unit of issue, level, month and year of pack, and gross weight.

c. The Marine Corps will provide the Contractor with the shipping address(es) for delivery of the repaired equipment. The Contractor shall be responsible for arranging for shipment to the pre-designated site(s). The Marine Corps will be responsible for transportation costs associated with shipping the subject equipment to and from the Contractor.

3.3 Government Furnished Equipment (GFE)/Government Furnished Materiel (GFM). The Management Control Activity (MCA/Code 573-2) will coordinate Government Furnished Equipment/Government Furnished Materiel (GFE)/(GFM) requests and maintain a central control system on all government owned assets in the contractor's possession. The MCA will forward a GFE Accountability Agreement to the contractor for signature on an annual basis to establish a chain of custody and identify property responsibilities for Marine Corps assets. The contractor is to acknowledge receipt of GFM to the MCA within 15 days of receipt. (This can be done by mailing (Materiel Management Department, Management Control Activity (Code 573-2) 814 Radford Blvd., STE 20320, Albany, GA 31704-0320) or faxing (commercial 229-639-5498 or DSN 567-5498) a copy of the DD1348).

3.4 Quality Assurance Provisions. The Contractor shall provide and maintain a Quality System that, as a minimum, adheres to the requirements of ANSI/ISO/ASQC Q9002-1994, Quality System-Model for Quality Assurance in Production, Installation and Servicing.

3.5 Contractor Furnished Materiel (CFM). The Contractor may requisition materiel as required in the performance of the SOW through the DoD Supply System. DoD 4000.25-1-M (MILSTRIP) Chapter 11 provides guidance to contractors on the requisitioning process. The

contractor's decision to utilize CFM procured from the DoD Supply System shall be based upon cost effectiveness, availability of materiel and the required completion/delivery date.

3.6 Acceptance. The performance of the Contractor and the quality of work delivered, including all equipment furnished and documentation written or compiled, shall be subject to in-process review and inspection during performance. Inspection may be accomplished in-plant or at any work site or location, and MCSC (Code CBG), Albany, Georgia representatives shall be permitted to observe the work or to conduct an inspection. Final inspection and acceptance testing shall be conducted at the Contractor's Facility. Final acceptance shall be conducted on 100 percent of items to verify that the units meet all requirements.

3.7 Rejection. Failure to comply with any of the specified requirements listed herein shall be reason for rejection by MCSC, (Code CBG), Albany, Georgia representative. The Contractor shall, at no additional cost to MCSC, (Code CBG), Albany, Georgia, correct the deficiencies and repeat the verification until an acceptable compliance with acceptance test procedures is demonstrated.

4.0 REPORTS.

4.1 Monthly Progress Reports. The Contractor shall provide Monthly Progress Reports summarizing the progress and status of the REBUILD Program. This report will consist of the Marine Corps Serial Number, date received into the REBUILD process, date completed. Also, total quantity received/completed, and total pending repair. This report shall be sent to Marine Corps Systems Command, (Code CBG), 814 Radford Blvd., Suite 20320, Albany, Georgia 31704-0320. This report will be in hard copy.

4.2 BRS Reporting. Report all BRS action to: Naval Surface Warfare Center (Code 2043), Crane Division, 2524 Highway 433, Crane, Indiana 47522-5020, DSN: 482-5845. Info: Marine Corps Systems Command (Code CBG), 814 Radford Blvd., Suite 20320, Albany, Georgia 31704-0320.

(1 Data Item)

OMB No. 0704-0188

**18. ESTIMATED
TOTAL PRICE**